



# United States Department of the Interior

3500 (017)

BUREAU OF LAND MANAGEMENT  
Rio Puerco Resource Area  
3550 Pan American Freeway, NE  
P.O. Box 6770  
Albuquerque, New Mexico 87107

1984 MAR 28 PM 1:34

330

26 MAR 1984

ADMIN.
ASST.
CHIEF
LEASE COMPL.
APPROVALS
FILE

## Memorandum

To: Area Director, Navajo Area Office, BIA


From: Environmental Scientist, Rio Puerco Resource Area

Subject: Supplemental Exploration Plan, Todilto Exploration and Development Corporation, Navajo Allotted Lease NOO-C-14-20-8396

Enclosed for your files and those of the Superintendent, Eastern Navajo Agency, are two copies each of the subject exploration plan and our approval letter.

Enclosures

*John M. [Signature]*



Rio Puerco Resource Area  
3550 Pan American Freeway. NE  
P.O. Box 6770  
Albuquerque, New Mexico 87107

20 MAR 1984

Mr. Toren K. Olson  
Geologist  
Todilto Exploration and Development Corporation  
3810 Academy Parkway South NE  
Albuquerque, New Mexico 87109

Dear Mr. Olson:

We have reviewed your plan to construct approximately 1,850 feet of exploration road on Navajo Allotted Lease N00-C-14-20-8396 (your request dated March 2, 1984). The plan is satisfactory and is approved.

Any future request for drill road construction on this lease should be submitted as a supplemental exploration plan in the format described in our Uranium Exploration Drilling Requirements as revised May 20, 1980.

Please notify this office at least two days before starting work.

Sincerely,

[ORIG: SGD.] HERRICK E. HANKS

Herrick E. Hanks  
Rio Puerco Resource Area  
Manager

cc:  
Area Director, NAO, BIA  
Superintendent, ENA, BIA

EXPLORATION AND DEVELOPMENT CORPORATION

G. WARNOCK  
PRESIDENT

H. B. (CHICK) WARNOCK  
SENIOR VICE PRESIDENT

V. MONDRAGON  
VICE PRESIDENT/CONTROLLER

J. N. DEMETRIOU  
VICE PRESIDENT  
CONSTRUCTION/ENGINEERING

March 2, 1984

Mr. Dale Jones  
District Mining Office  
500 Gold Avenue, SW-Room 116  
Albuquerque, New Mexico 87102

Re: BIA Lease #N00-C-14-20-8396  
SW $\frac{1}{4}$  Section 18, T13N, R10W

Dear Mr. Jones:

The 1984 exploration assessment work on the above-referenced lease will consist of approximately 1,850 feet of road construction. The road is plotted on the attached map (#103-007-015-18-D-13).

We will contact you by phone at least two days prior to starting work.

Sincerely,

*Diane Warnock*

for Toren Olson

TKO:dtw  
Enclosure

MINERALS, RIO PUERCO RA  
RECEIVED

MAR 14 1984  
BUREAU OF LAND MANAGEMENT  
ALBUQUERQUE, NEW MEXICO

DMO Albuquerque STATE NMDATE OF INSPECTION 05/22/84

SERIAL NUMBER OF TRACT	HOLDER OF PRIMARY TRACT INTEREST	TRACT STATUS	NUMBER OF INSPECTIONS	HOURS OF INSPECTION ONSITE/TOTAL	COMMODITY	TRACT TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN 7
N00-C-14-20-8396	TEDCO	Explor.	1	1 / 3	Uranium	Lease
				/		
				/		
				/		
				/		
				/		
				/		
				/		
				/		
				/		

TYPE OF INSPECTION (CHECK ONE) / / MINE / ☒ / EXPLORATION / / MINE ABANDONMENT  
/ / TECH EXAM, EA / / INACTIVE / / OTHER

PURPOSE OF INSPECTION Examination of ongoing operations and lease conditions.BRIEF DESCRIPTION OF INSPECTION TEDCO constructed a exploration drill hole road under its approved exploration plan. No violations of the lease terms or approved exploration plan were observed.

MINE NAME \_\_\_\_\_ DESIGNATED OPERATOR \_\_\_\_\_  
DATE ORIGINAL MINE PLAN SUBMITTED \_\_\_\_\_ DATE ORIGINAL MINE PLAN APPROVED \_\_\_\_\_  
DATE MODIFIED MINE PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED MINE PLAN APPROVED \_\_\_\_\_  
IF APPROVED PLAN IS PENDING MODIFICATION, GIVE BRIEF DESCRIPTION OF MODIFICATION: \_\_\_\_\_

DATE ORIGINAL EXPL. PLAN SUBMITTED 04/01/80 DATE ORIGINAL EXPL. PLAN APPROVED 06/23/80  
DATE MODIFIED EXPL. PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED EXPL. PLAN APPROVED \_\_\_\_\_

BLM INSPECTOR(S) AND TITLES(S) George R. Tetreault, Jr., Mining EngineerSURFACE MANAGEMENT AGENCY FOR TRACT(S) Bureau of Indian AffairsNAME, TITLE, AND OFFICE OF SMA PERSONNEL PARTICIPATING IN INSPECTION  
NoneNAME, TITLE, AND OFFICE OF OSM OR REGULATORY AUTHORITY PERSONNEL PARTICIPATING IN INSPECTION  
NoneNAME, TITLE, AND OFFICE OF COMPANY REPRESENTATIVE(S) PARTICIPATING IN INSPECTION  
NoneHOURS OF OFFICES TIME (PRE-INSPECTION) PREPARING FOR INSPECTION 0HOURS OF OFFICES TIME (POST-INSPECTION) REPORTING ON INSPECTION 1TOTAL TRAVEL TIME 1 TOTAL OFFICE TIME 1

WAS A CONDITION OF NONCOMPLIANCE ENCOUNTERED DURING INSPECTION? / / YES / ☒ / NO  
IF YES, PREPARE NONCOMPLIANCE REPORT

WAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? / / YES / ☒ / NO  
IF YES, PREPARE UNDESIRABLE EVENT REPORT

PERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION

original:

Area Director, NAD, BIA

George R. Tetreault, Jr.

*dvmorgan*  
JUL - 2 1985

Area Real Property Management Officer, Navajo

Release of Navajo Allotted Uranium Lease Nos. N00-C-14-20-5681 and -8396

Area Manager, Rio Puerco Resource Area, Bureau of Land Management,  
Albuquerque, New Mexico

Attached for your necessary review are copies of the following Statement To  
Accompany Release and Release of Uranium Lease for cancellation of Lease Nos.  
N00-C-14-20-5681 and -8396.

Please advise us if the said leases have been properly abandoned and whether  
the lessee can be released from liability. Also, we would appreciate return  
of the documents.

/s/ Floyd E Espinoza

Attachments

bcc: TRR/1105-13a ✓  
Minerals Chrono  
300

330:DVMORGAN:mbh:07/01/85p

BMO Albuquerque STATE NMDATE OF INSPECTION April 10, 1985

SERIAL NUMBER OF TRACT	HOLDER OF PRIMARY TRACT INTEREST	TRACT STATUS	NUMBER OF INSPECTIONS	HOURS OF INSPECTION ONSITE/TOTAL	COMMODITY	TRACT TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN 7
N00-C-14-20-5681	TEDCO	Active	1	.5 / 1.5	Uranium	Lease
N00-C-14-20-8396	TEDCO	Active	1	.5 / 1.5	Uranium	Lease
				/		
				/		
				/		
				/		
				/		
				/		
				/		
				/		

TYPE OF INSPECTION (CHECK ONE) / / MINE / XX / EXPLORATION / / MINE ABANDONMENT  
/ / TECH EXAM, EA / / INACTIVE / / OTHERPURPOSE OF INSPECTION To determine if necessary reclamation for relinquishment was completed.BRIEF DESCRIPTION OF INSPECTION Reclamation approximately half completed. Due to finish in  
two (2) days.MINE NAME \_\_\_\_\_ DESIGNATED OPERATOR \_\_\_\_\_  
DATE ORIGINAL MINE PLAN SUBMITTED \_\_\_\_\_ DATE ORIGINAL MINE PLAN APPROVED \_\_\_\_\_  
DATE MODIFIED MINE PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED MINE PLAN APPROVED \_\_\_\_\_  
IF APPROVED PLAN IS PENDING MODIFICATION, GIVE BRIEF DESCRIPTION OF MODIFICATION: \_\_\_\_\_DATE ORIGINAL EXPL. PLAN SUBMITTED 04/09/76 DATE ORIGINAL EXPL. PLAN APPROVED 06/28/76  
DATE MODIFIED EXPL. PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED EXPL. PLAN APPROVED \_\_\_\_\_BLM INSPECTOR(S) AND TITLES(S) George R. Tetreault, Jr., Mining Engineer ; Brian LloydSURFACE MANAGEMENT AGENCY FOR TRACT(S) Bureau of Indian Affairs

NAME, TITLE, AND OFFICE OF SMA PERSONNEL PARTICIPATING IN INSPECTION \_\_\_\_\_

NAME, TITLE, AND OFFICE OF OSM OR REGULATORY AUTHORITY PERSONNEL PARTICIPATING IN INSPECTION \_\_\_\_\_  
None

NAME, TITLE, AND OFFICE OF COMPANY REPRESENTATIVE(S) PARTICIPATING IN INSPECTION \_\_\_\_\_

HOURS OF OFFICES TIME (PRE-INSPECTION) PREPARING FOR INSPECTION 0  
HOURS OF OFFICES TIME (POST-INSPECTION) REPORTING ON INSPECTION 1  
TOTAL TRAVEL TIME 1.0 hr. TOTAL OFFICE TIME 1 hr.WAS A CONDITION OF NONCOMPLIANCE ENCOUNTERED DURING INSPECTION? / / YES / XX / NO  
IF YES, PREPARE NONCOMPLIANCE REPORTWAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? / / YES / XX / NO  
IF YES, PREPARE UNDESIRABLE EVENT REPORT

PERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION

George R. Tetreault, Jr.

INSPECTION RECORD  
SOLID MINERALS

OMO Albuquerque STATE NM

DATE OF INSPECTION April 4, 1985

SERIAL NUMBER OF TRACT	HOLDER OF PRIMARY TRACT INTEREST	TRACT STATUS	NUMBER OF INSPECTIONS	HOURS OF INSPECTION ONSITE/TOTAL	COMMODITY	TRACT TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN 7
N00-C-14-20-5681	TEDCO	Active	1	1 / 4	Uranium	Leased
N00-C-14-20-8396	TEDCO	Active	1	1 / 4	Uranium	Leased
				/		
Tess Mining				/		
Claims 1-10	TEDCO	Active	1	.5 / .5	Uranium	Mng. Claim
				/		
				/		
				/		
				/		
				/		

TYPE OF INSPECTION (CHECK ONE) / / MINE / XX / EXPLORATION / / MINE ABANDONMENT  
/ / TECH EXAM, EA / / INACTIVE / / OTHER

PURPOSE OF INSPECTION TEDCO plans to release these leases.

BRIEF DESCRIPTION OF INSPECTION Went over leases to determine what reclamation was needed for abandonment of lease and mining claims.

MINE NAME \_\_\_\_\_ DESIGNATED OPERATOR \_\_\_\_\_  
DATE ORIGINAL MINE PLAN SUBMITTED \_\_\_\_\_ DATE ORIGINAL MINE PLAN APPROVED \_\_\_\_\_  
DATE MODIFIED MINE PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED MINE PLAN APPROVED \_\_\_\_\_  
IF APPROVED PLAN IS PENDING MODIFICATION, GIVE BRIEF DESCRIPTION OF MODIFICATION: \_\_\_\_\_

DATE ORIGINAL EXPL. PLAN SUBMITTED \_\_\_\_\_ DATE ORIGINAL EXPL. PLAN APPROVED \_\_\_\_\_  
DATE MODIFIED EXPL. PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED EXPL. PLAN APPROVED \_\_\_\_\_

BLM INSPECTOR(S) AND TITLES(S) George R. Tetreault, Jr., Mining Engineer ; Brian Lloyd

SURFACE MANAGEMENT AGENCY FOR TRACT(S) Bureau of Indian Affairs

NAME, TITLE, AND OFFICE OF SMA PERSONNEL PARTICIPATING IN INSPECTION  
John Sanchez, ENA, BIA

NAME, TITLE, AND OFFICE OF OSM OR REGULATORY AUTHORITY PERSONNEL PARTICIPATING IN INSPECTION  
None

NAME, TITLE, AND OFFICE OF COMPANY REPRESENTATIVE(S) PARTICIPATING IN INSPECTION:  
Toren Olsen; Norm Dirks

HOURS OF OFFICES TIME (PRE-INSPECTION) PREPARING FOR INSPECTION 1  
HOURS OF OFFICES TIME (POST-INSPECTION) REPORTING ON INSPECTION 1  
TOTAL TRAVEL TIME 4 TOTAL OFFICE TIME 2

WAS A CONDITION OF NONCOMPLIANCE ENCOUNTERED DURING INSPECTION? / / YES / XX / NO  
IF YES, PREPARE NONCOMPLIANCE REPORT

WAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? / / YES / XX / NO  
IF YES, PREPARE UNDESIRABLE EVENT REPORT

PERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION

George R. Tetreault, Jr.

APR 17 1985  
NAVAJO AREA OFFICE  
BR OF REAL PROPERTY MGMT.

INSPECTION RECORD  
SOLID MINERALS

1 DMO Albuquerque STATE NM

DATE OF INSPECTION 8/7/84

SERIAL NUMBER OF TRACT	HOLDER OF PRIMARY TRACT INTEREST	TRACT STATUS	NUMBER OF INSPECTIONS	HOURS OF INSPECTION ONSITE/TOTAL	COMMODITY	TRACT TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN 7
NOO-C-14-20-5681	TEDCO	Active	1	0.5/ 1.0	Uranium	Lease
(-8396)	"	"	1	0.5/ 1.0	"	"
				/		
				/		
				/		
				/		
				/		
				/		
				/		
				/		

7 TYPE OF INSPECTION (CHECK ONE) / / MINE / XX / EXPLORATION / / MINE ABANDONMENT  
8 / / TECH EXAM, EA / / INACTIVE / / OTHER

10 PURPOSE OF INSPECTION General lease inspection by helicopter.

12 BRIEF DESCRIPTION OF INSPECTION Lease surface generally in good shape. See photos (attached)  
13 of last years dilligency work completed.

15 MINE NAME \_\_\_\_\_ DESIGNATED OPERATOR \_\_\_\_\_  
16 DATE ORIGINAL MINE PLAN SUBMITTED \_\_\_\_\_ DATE ORIGINAL MINE PLAN APPROVED \_\_\_\_\_  
17 DATE MODIFIED MINE PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED MINE PLAN APPROVED \_\_\_\_\_  
18 IF APPROVED PLAN IS PENDING MODIFICATION, GIVE BRIEF DESCRIPTION OF MODIFICATION: \_\_\_\_\_

11 DATE ORIGINAL EXPL. PLAN SUBMITTED 04/09/76 DATE ORIGINAL EXPL. PLAN APPROVED 06/28/76  
12 DATE MODIFIED EXPL. PLAN SUBMITTED \_\_\_\_\_ DATE MODIFIED EXPL. PLAN APPROVED \_\_\_\_\_

14 BLM INSPECTOR(S) AND TITLES(S) George R. Tetreault, Jr., Mining Engineer;  
15 George Laskar, Chief Minerals Staff

16 SURFACE MANAGEMENT AGENCY FOR TRACT(S) Bureau of Indian Affairs

18 NAME, TITLE, AND OFFICE OF SMA PERSONNEL PARTICIPATING IN INSPECTION \_\_\_\_\_

20 NAME, TITLE, AND OFFICE OF OSM OR REGULATORY AUTHORITY PERSONNEL PARTICIPATING IN INSPECTION  
21 None

22 NAME, TITLE, AND OFFICE OF COMPANY REPRESENTATIVE(S) PARTICIPATING IN INSPECTION \_\_\_\_\_

25 HOURS OF OFFICES TIME (PRE-INSPECTION) PREPARING FOR INSPECTION 0

26 HOURS OF OFFICES TIME (POST-INSPECTION) REPORTING ON INSPECTION 1

27 TOTAL TRAVEL TIME 0 TOTAL OFFICE TIME 1

29 WAS A CONDITION OF NONCOMPLIANCE ENCOUNTERED DURING INSPECTION? / / YES / XX / NO  
30 IF YES, PREPARE NONCOMPLIANCE REPORT

32 WAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? / / YES / XX / NO  
33 IF YES, PREPARE UNDESIRABLE EVENT REPORT

35 PERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION \_\_\_\_\_

George R. Tetreault, Jr.

original:

Area Director, NAO, BIA